




CORAL



HALMAR

HALMAR Sp. z o.o., ul. Centralnego Okręgu Przemysłowego 2,
37-450 Stalowa Wola, POLSKA / POLAND
tel. + 48 15 843 28 10, fax: +48 15 842 19 57, e-mail: office@halmar.com.pl




CORAL




HALMAR

HALMAR Sp. z o.o., ul. Centralnego Okręgu Przemysłowego 2,
37-450 Stalowa Wola, POLSKA / POLAND
tel. + 48 15 843 28 10, fax: +48 15 842 19 57, e-mail: office@halmar.com.pl













S H30-400mm x2	T 6x	U ø13 24x		
	W 5x	X 4x22 10x	Y 4x	Z 4x
Z1 3,5x16 8x	Z2 ø4,2x50 1x	Z3 1x	Z4 3,5x16 12x	Z5 ø1,4x20 80x
Z6 5x13 30x	Z7 ø8x50 1x	Z8 ø8x30 38x	Z9 22x	Z10 ø15x12 22x
Z11 ø7x50 32x	Z12 1x	Z13 3x	Z14 1x	Z15 ø16 22x




Z		4x
T		6x
Z10		2x
ø15x12		2x
Z9		4x
Z8		6x
ø8x30		

1












3



Z10		8x
Ø15x12		
Z9		6x
Z8		8x
Ø8x30		






4





5

Z11



Z11		
Ø7x50		2x
Z12		
		1x

6




7



Z11

 Ø7x50



3x


Z12


1x






8



Z11  Ø7x50 6x	Z12  1x
---	--


9



Z11  Ø7x50	Z12  13x
---	---

9/27

10






A=B


Z5


Ø1,4x20



80x




11




X		
4x22		10x
W		
		5x

Z2  ø4,2x50 1x	Z6  5x13 4x	Z14  1x	Z4  3,5x16 2x	Z3  1x
--	---	--	---	---


12

Z7  ø8x50 1x


1






2





3




4




13



8x








ø15x12





8x

ø8x30

16x




14







ø7x50


8x



1x



15




2x




$a=b$








Z4  3,5x16	S 
Z13  2x	10x  H30-400mm
	Z6  5x13
	x2 16x








2x




16





18



Z6 5x13	2x	U ø13	24x
		Z15 ø16	22x
		Z13	1x

