

CUBUS

A  x1	H  x5
B  x1	I  x2
CL  x1	J  M6x16 x10
CR  x1	K  x10
D  x1	L  M6x30 x6
E  x1	M  M6x25 x4
F  x5	N  M8x25 x3
G  x1	O  x1
	P  x1

